

## **FREEZE UP IN EFFECT**

Thunder Bay Hydro has discontinued underground service installations during the freeze-up period of November 15, 2010 to May 15, 2011.

During freeze-up, all customers, including residential customers in subdivisions, are responsible for the digging and backfilling of their own trench for all underground services.

For any further information and options, please contact Thunder Bay Hydro Power Systems at 343-1176.



**Visit us online at [www.tbhydro.com](http://www.tbhydro.com)**